



REPAIR - DIV L
 Hermits Peak NM-SNF-000027
 Calf Canyon NM-SNF-000028

6/1/2022
 Day

Event Line Repair Status	Event Point Repair Status	Completed - Inspected	Di Site	Staging Area	Stream Crossing	Deer Push	AA Completed Fuel Break	Fence	Wildfire Daily Fire Perimeter	US or State Highway	Ranger District Boundary
In Use - Fire Management	In Use - Fire Management	No Repair Needed	Lookout	Value at Risk	Road Repair	Culvert	Completed Hand Line	Other	US or State Highway	Local Road	Federal Wilderness Boundary
Needs Assessment	Needs Assessment	Other - See Comments	Unimproved Landing Area	Gate	Retardant in Avoidance Area	Hazard	Completed Mixed Construction Line	Repair Line	Local Road	4WD Road	State Boundary
Repair Needed	Repair Needed		X Division Break	Water Development or Draft Site	Repair Point	Water Source	Completed Road as Line	Retardant Drop	Secondary Highway	Paved Roads	County Boundary
No Repair Needed	Completed - Ready for Inspection		Drop Point	Camp	Hazard Tree	Completed Burnout	Access or Improved Road	Contained	Other	Other	
Other - See Comments					Fence - Cut/Damaged	Completed Dozer Line		Uncontained	Other		



130000 - SWNM72 GISS - 6/1/2022 1112 - Acres from IR and GPS - North American 1983 Datum, Lat/Long Grid