



**Repair Legend**

○ In Use - Fire Management (120)	○ In Use - Fire Management (134)
○ Needs Assessment (144)	○ Needs Assessment (81)
○ Repair Needed (691)	○ Repair Needed (466)
○ In Progress (1)	○ In Progress (9)
○ Completed - Ready for Inspection (7)	○ Completed - Ready for Inspection (19)
○ Completed - Inspected (79)	○ Completed - Inspected (152)
○ No Repair Needed (90)	○ No Repair Needed (101)
○ Other - See Comments (8)	○ Other - See Comments (2)

**REPAIR - DIV L**

Hermits Peak NM-SNF-000027  
Calf Canyon NM-SNF-000028

6/13/2022  
Day

○ Dip Site	■ Camp	○ Gate	○ Retardant in Avoidance Area	○ Fence - Cut/Damaged	○ Completed Dozer Line	○ Access or Improved Road	○ Uncontaminated	○ Paved Roads	○ Administrative FS Boundary	○ County Boundary
○ Heliport	■ Staging Area	○ Bridge	○ Resource Location	○ Dozer Push	○ Completed Fuel Break	○ Road	○ Wildfire Daily Fire Perimeter	○ Dirt (Not Paved)	○ Ranger District Boundary	
○ Unimproved Landing Area	○ Lookout	○ Water Development or Draft Site	○ Repair Point	○ Culvert	○ Completed Hand Line	○ Other	○ US or State Highway	○ Local Road	○ Federal Wilderness Boundary	
○ Division Break	○ Hot Spot - Spot Fire	○ Stream Crossing	○ Landing or Log Deck	○ Hazard	○ Construction Line	○ Repair Line	○ Local Road	○ US or State Highway	○ State Boundary	
○ Drop Point	○ Value at Risk	○ Road Repair	○ Hazard Tree	○ Completed Burnout	○ Completed Road as Line	○ Retardant Drop	○ 4WD Road			
○ Other	○ Other					○ Contained				



134,000 - SWNM72 GIS - 6/12/2022 2:59 - Acres from IR and GPS - North American 1983 Datum, LatLong Grid