



●	In Use - Fire Management (96)	●	In Use - Fire Management (126)
●	Needs Assessment (164)	●	Needs Assessment (51)
●	Repair Needed (200)	●	Repair Needed (206)
●	In Progress (8)	●	In Progress (2)
●	Completed - Ready for Inspection (0)	●	Completed - Ready for Inspection (6)
●	Completed - Inspected (96)	●	Completed - Inspected (261)
●	No Repair Needed (111)	●	No Repair Needed (112)
●	Other - See Comments (11)	●	Other - See Comments (5)

REPAIR - BRANCH XI

Hermits Peak NM-SNF-000027
Calf Canyon NM-SNF-000028

6/13/2022
Day

● Dip Site	■ Branch Break	■ Staging Area	● Bridge	● Resource Location	● Culvert	■ Completed Dozer Line	■ Access or Improved Road	■ Uncontained	■ Primary Highway	■ 4WD Road	■ National Designated	■ Ranger District Boundary
● Helibase	■ Zone Break	■ Lookout	● Water Development or Draft Site	● Repair Point	● Clean Up Area	■ Completed Fuel Break	■ Fence	■ Wildfire Daily Fire Perimeter	■ Secondary Highway	■ Interstate Highway	■ Trail	■ Federal Wilderness Boundary
■ Unimproved Landing Area	■ Medical	■ Incident Command Post	● Structure Wrap	● Landing or Log Deck	● Safety Zone	■ Completed Mixed Construction Line	■ DIRT (Not Paved)	■ US or State Highway	■ Paved Roads	■ US or State Highway	■ Runway	■ Approved or Proclaimed USFS Boundary
■ Division Break	■ Drop Point	■ Gate	● Stream Crossing	● Hazard Tree	● Hazard	■ Completed Road as Line	■ Local Road	■ Local Road	■ Local Road	■ Local Road	■ Local Road	■ State Boundary
			● Road Repair	● Fence - Cut/Damaged	● Water Source	■ Restricted Water Source	■ Retardant Drop					

150000 - SWANM72 GSS - 6/13/2022 04:31 - Acres from IR and GPS - North American 1983 Datum, Laidong Grid

