



Repair Legend	
●	Event Point
●	Needs Assessment (85)
●	Repair Needed (155)
●	In Progress (2)
●	Completed - Ready for Inspection (24)
●	Completed - Inspected (80)
●	Other - See Comments (14)
—	Event Line
—	In Use - Fire Management (86)
—	Needs Assessment (72)
—	Repair Needed (310)
—	Completed - Ready for Inspection (64)
—	Completed - Inspected (440)
—	Other - See Comments (16)
★	Property Owner Contact Status
★	Made Contact - No Access (0)
★	Made Contact - Permission Granted (0)
★	No Contact - Revisit (0)
■	No Data (0)

REPAIR NORTH ZONE
 Hermits Peak NM-SNF-000027
 Calf Canyon NM-SNF-000028

6/23/2022
 Day
 341,471 acres at
 06/19/2022 17:00

- | | | | | |
|--|--|--|--------------------------------------|--|
| ● Helipoint | ● Water Development or Draft Site | ◆ Repeater | H— Completed Hand Line | ★ Made Contact - No Access |
| ● Drop Point | ● Stream Crossing | ▲ Safety Zone | M— Completed Mixed Construction Line | ★ Made Contact - Permission Granted |
| ● Staging Area | ● Repair Point | — Completed Burnout | P— Completed Plow Line | ★ No Contact - Revisit |
| ● Other | ● Landing or Log Deck | — Completed Dozer Line | R— Completed Road as Line | ■ No Data |
| ● Gate | ● Road Repair | — Completed Fuel Break | — Access or Improved Road | |
| | ● Retardant in Avoidance Area | — Completed Road as Line | — Fence | |
| | ● Resource Location | — Completed Fuel Break | — Highlighted Feature | |
| | ● Clean Up Area | — Completed Fuel Break | — Zone Break | |
| | | — Completed Fuel Break | — Federal Wilderness Boundary | |
| | | — Completed Fuel Break | — Wildlife Daily Fire Perimeter | |

141,719 - 2022-06-22 20:35 - Acres from IR and GPS - North American 1983 Datum, Lanting Old

