


Repair Legend	
○	In Use - Fire Management
○	Needs Assessment
○	Repair Needed
○	In Progress
○	Completed - Ready for Inspection
○	Completed - Inspected
○	No Repair Needed
○	Other - See Comments
○	In Use - Fire Management
○	Needs Assessment
○	Repair Needed
○	In Progress
○	Completed - Ready for Inspection
○	Completed - Inspected
○	No Repair Needed
○	Other - See Comments

REPAIR BRIEFING
DIV C
 Hermits Peak NM-SNF-000027
 Calf Canyon NM-SNF-000028

7/16/2022
 Day
 341,735 acres at
 7/5/2022 at 19:00

- Power Lines
- Forest Service
- Administrative FS Boundary
- Ranger District Boundary
- Federal Wilderness Boundary
- Bureau of Land Management (BLM)
- National Park Service (NPS)
- State
- US Forest Service (USFS)
- Private
- Other Property
- Water Tank
- Sling Site
- Division Break
- Drop Point
- Camp
- Staging Area
- Lookout
- Value at Risk
- Completed Dozer Line
- Completed Fuel Break
- Completed Hand Line
- Completed Mixed Construction Line
- Completed Road as Line
- Access or Improved Road
- Fence
- Other
- Repair Line
- Retardant Drop
- Division Areas
- Wildfire Daily Fire Perimeter



SOUTHWEST AREA
INCIDENT MANAGEMENT TEAM 4

138,000 - SWM14 - 7/15/2022 2:17 - Acres from RL and GPS - North American 1983 Datum, LatLong Grid