



# NORTH REPAIR

### Repair Status

- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Other - See Comments
- ⬮ Needs assessment
- ⬮ Repair Needed
- ⬮ In Progress
- ⬮ Completed

## Calf Canyon

NMSNF000028

9/18/2022

## SUPPRESSION REPAIR NORTH

- |                       |                           |                        |                 |                                   |                               |                           |                                     |                        |                               |                            |                                   |                    |
|-----------------------|---------------------------|------------------------|-----------------|-----------------------------------|-------------------------------|---------------------------|-------------------------------------|------------------------|-------------------------------|----------------------------|-----------------------------------|--------------------|
| ● Aerial Hazard       | ● Unimproved Landing Area | ■ Closure              | ● Value at Risk | ● Bridge                          | ● Retardant in Avoidance Area | ● Fence - Cut/Damaged     | ◆ Repeater                          | ⬮ Completed Burnout    | — Completed Plow Line         | — Repair Line              | — Bureau of Indian Affairs (BIA)  | — Important Routes |
| ● Airstrip or Airport | ✕ Division Break          | ■ Camp                 | ● Other         | ● Water Development or Draft Site | ● Resource Location           | ◆ Dozer Push              | ▲ Safety Zone                       | ⊗ Completed Dozer Line | — Completed Road as Line      | — Road Repair              | — Bureau of Land Management (BLM) | —                  |
| ● Dip Site            | ■ Medical                 | ■ Staging Area         | ● Landmark      | ● Structure Wrap                  | ● Repair Point                | ▲ Hazard                  | ▲ Hazard                            | ⊗ Completed Fuel Break | — Access or Improved Road     | — Ranger District Boundary | — State                           | —                  |
| ● Helispot            | ■ Incident Command Post   | ■ Lookout              | ● Gate          | ● Stream Crossing                 | ● Landing or Log Deck         | ● Water Source            | ● Water Source                      | — Completed Hand Line  | — Administrative FS Boundary  | — US Forest Service (USFS) | —                                 | —                  |
| ● Helibase            | ■ Drop Point              | ● Hot Spot - Spot Fire | ● Fire Station  | ● Road Repair                     | ● Hazard Tree                 | ● Restricted Water Source | — Completed Mixed Construction Line | — Other                | — Federal Wilderness Boundary | — Private                  | —                                 | —                  |

GIS Calculated Acres from IR and GPS

341,735 acres as of 7/5/2022 at 19:00

NAD 1983 UTM Zone 13N

Created 9/18/2022 10:55

SOUTHWEST AREA INCIDENT MANAGEMENT TEAM 5