


SUPPRESSION REPAIR

Mile Post 16 | CA-HIA-582/583 | July 14, 2026 Day

FC Line Type	Label	Repair Status	Length Feet	GISS Miscellaneous
Completed Dozer Line	DL1	Repair Needed	8469	1.6 Miles
Completed Dozer Line	DL2	In Progress	2079	0.4 Miles
Completed Dozer Line	DL3	In Progress	1651	0.3 Miles
Completed Hand Line	HL1	Completed - Inspected	1303	0.2 Miles
Completed Hand Line	HL2	Completed - Inspected	1526	0.3 Miles
Completed Hand Line	HL3	Completed - Inspected	783	0.2 Miles
Completed Hand Line	HL4	Completed - Inspected	2386	0.5 Miles
Road Repair		In Progress	15426	2.9 Miles



SUPPRESSION REPAIR

Mile Post 16
CA-HIA-582/583
July 14, 2026 Day

104 acres at 07/11/2026 1830 PDT

1:5,000 | Acres from IR and GPS
NCIIMT3 | 7/13/2026 2159
WGS 1984 Datum, LatLong Grid

Repair Status

- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- No Repair Needed
- Repair Deferred

Other - See Comments

- Structures
- Division Break
- Restricted Water Source
- Completed Dozer Line
- Completed Hand Line
- Road Repair

Contained Fire Edge

- Wildfire Perimeter
- Highway
- Arterial Road
- Improved Road
- Unimproved Road

Miles

0 0.1 0.2