





Repair

Bug
NV-CCD-030683
October 2026

93,733 acres at 08/17/2026

0 0.5 1 1.5 2 2.5
Miles



1:49,281 | B. MacDougall | 9/28/2026 1557
Acres from IR and GPS
NAD 1983 2011 Datum, LatLong Grid

Group C

Group B

- Water Tank
- Division Break
- Hazard
- Drop Point
- Camp
- Draft Site
- Hydrant
- Repeater
- Other
- Landmark
- Gate
- Bridge
- Stream Crossing
- Road Repair
- Resource Location
- Repair Point
- Fence - Cut/Damaged
- Invasive Plant
- Dozer Push
- Clean Up Area
- Hoselay
- Completed Dozer Line
- Completed Fuel Break
- Completed Hand Line
- Completed Road as Line
- Fence
- Other
- Road Repair
- Access Route

- Needs Assessment
- Repair Needed
- Completed - Ready for Inspection
- Completed - Inspected
- No Repair Needed

