Repair

DIV S

Little Giant

WA-OWF-260406

9/15/2026

172,705 acres at 09/14/2026 at 1934 hrs

1:40,000 | NWIMT12 | 9/15/2026 0616
Acres from IR and GPS
North American 1983 Datum. LatLong Grid

- Division Break
- Hazard
- Hazard Tree
- Helispot
- Sling Site
- Unimproved Landing Area
- UAS Launch and Recovery
- Lookout
- Drop Point
- Closure
- Staging Area
- Dip Site
- Draft Site
- Hydrant
- Mobile Weather Unit
- Repeater
- Value at Risk
- Gate
- Bridge
- Structure Wrap
- Stream Crossing
- Road Repair
- Resource Location
- Repair Point
- Landing or Log Deck
- Slash Pile
- Fence - Cut/Damaged
- Dozer Push
- Culvert
- Clean Up Area
- Other Property
- Pump
- Water Tank
- Completed Dozer Line
- Completed Fuel Break
- Completed Hand Line
- Completed Mixed Construction Line
- Completed Plow Line
- Completed Road as Line
- Fence
- Repair Line
- Road Repair
- Access Route
- Contained Fire Edge
- Uncontained Fire Edge
- Wildfire Perimeter
- Depression Index
- Depression Intermediate
- Normal Index
- Normal Intermediate

Repair Status

- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- Repair Deferred
- Other - See Comments

0 1 2 3 Miles