

PHOTOS – SOIL AND WATERSHED



High soil burn severity along riparian corridor and low soil burn severity with greenup on floodplain in Bruneau Canyon



Riparian condition and sheet erosion resulting from first post-fire storm in upper Bruneau Canyon



Four-inch depth of erosion on debris cone during first post-fire storm.



Road #067 wash out and channel scour on debris cone at Little Cottonwood Creek



Ash and mud deposition on floodplain from first post-fire storm



Plugged culvert outlet on Road #751