

PHOTOS – CULTURAL



Burned cabin at Scott Ranch



Parks Mill - note burned wall-support timbers



Partially burned trestle - note proximity of vegetation



Tequero Dips stone building - note fire-blackened wall



Unburned cabin - note clearing in front of structure



Unburned cabin - note the remaining vegetation hazard