




Chimney Tops 2 BAER

Trail and Hazard Tree Assessment



No warranty expressed or implied is made regarding the accuracy or utility of the data and information on this map.

- | | | | | | |
|--|-----------------------------|--|-----------------|--|----------------|
| | Trail Infrastructure Damage | | 4WD | | Fire Perimeter |
| | Hazard Trees | | Local | | Park Boundary |
| | Trailhead | | Primary | | |
| | Trails | | Service/Unknown | | |

